

Navy Broadway Complex. Appendix 8D Volume II. Summary of Comments.

Page: 6

Net New Trips 7,100.

Page: 26

Archaeological Subsurface Investigation of Navy Broadway Complex.

Page: 27

Figure 4-66 Archeology Trench Location Map.

Page: 46

4.11.1 Affected Environment. Hazardous Materials. Twenty borings were conducted throughout the site. Monitoring wells were installed in 10 of those boring wells. Soil samples were taken from above the water table, which is 8 to 10 feet below grade. Figure 4-72 depicts the location where samples were taken.

Page: 47

Figure 4-72. Location of Soil Sample Borings.

Page: 69

Section 6 - Growth-Inducing Impacts.